



WEST BENGAL POLLUTION CONTROL BOARD

(Department of Environment, Govt. of West Bengal)

Paribesh Bhawan

Bldg. No. 10A, LA Block, Sector-III, Salt Lake City

Kolkata-700 098

Tel: 2335-9088, 2335-7428, 2335-8211, 2335-8073, 2335-6731

2335-0261, 2335-8212, 2335-8213, 2335-8861, 2335-5975

Fax: (0091) (033) 2335-6730 / 2335-2813

MEMO NO.: 0292 -136-WPB-SEE-K.O.-GEN/2003

DATED : 19-04-2007

DIRECTION

WHEREAS **M/S. SHIV SHANKAR SPONGE IRON** (hereinafter referred as the industry) operates its sponge iron unit at Vill. – Dantia, P. O. – Shyamnagar, Dist. – Purulia

WHEREAS, an inspection was carried out by the Regional Officer of the WEST BENGAL POLLUTION CONTROL BOARD (hereinafter referred as the Board) on 09-11-2006 and observed the following:

1. The industry is not complying with the emission standard for various unit operations of the 1st rotary kiln namely, kiln, coal crusher, cooler discharge section and product house.
2. The industry is operating an additional 50 TPD rotary kiln without obtaining “NOC” and “Consent-to-Operate” from the Board

WHEREAS, a hearing was conducted involving the industry on 23-03-2007 at the Head Office of the West Bengal Pollution Control Board.

NOW THEREFORE, in exercise of the powers conferred under Air (Prevention & Control of Pollution) Act, 1981 and Environment (Protection) Act, 1986 and Rules made thereunder **M/S. SHIV SHANKAR SPONGE IRON**. is hereby directed as follows:

1. That, the industry is allowed six months time to improve the efficacy of the emission control system and comply with the emission standard.
2. **That, the industry should submit a Bank Guarantee (proforma enclosed) for Rs.4.00 Lakh (Rupees Four Lakhs only) to ensure compliance with the environmental norms in future.**
3. That, that industry should always operate its pollution abatement systems during its manufacturing operation.
4. That, the industry should take a shut down of its manufacturing activity whenever the pollution abatement system fails to function due to whatever reason and the same should be intimated to the Board.
5. That, the industry should dismantle its 50 TPD capacity 2nd rotary kiln and submit a compliance report to the Board

In case of the non-compliance of the above directions by the industry within the stipulated time, the Board may have to issue necessary regulatory order without any further reference.

This has the approval of the Competent Authority.

By Order

Sd/-

(Dr. D. Chakraborty)

**Chief Scientist & Head-Technical Cell
West Bengal Pollution Control Board**